

Supply package

1	TOPODRONE LiDAR
2	Protective cover for the laser scanner lens
3	Quick-release dovetail mount - or mount the laser scanner to the UAV in the DJI SkyPort payload slot with protective cover - optional
4	Spare antenna cable with connectors
5	GNSS antenna mount with cable and mounting screws
6	External GNSS antenna
7	MicroSD card at least 32 GB
8	External USB Type-C flash drive not less than 32 GB
9	OTG USB Type-C to USB Type-A adapter
10	Cloth for wiping the lens
11	Power supply 220V (USB Type-C) for power supply (PD 12-15-20V)
12	USB-Type-C to LEMO 6-PIN power cable for power supply power supply
13	M3x8 screws for attaching TOPODRONE LiDAR to the mount with DJI SkyPort connector
14	Protective carrying case with a lodgement for transportation

Revision #2

Created 23 October 2024 16:37:04 by Support 1

Updated 23 October 2024 18:58:29 by Support 1